GFIAA Airfield Maintenance Facility Expansion & Renovation

Project Definition Notes

1/16/2025 update 4/10/2025

Existing Building assessment (Dec 2024):

- 1. Bldg is approx. 25 years old
- 2. Typical upgrades for electrical
- 3. Essentially total replacement of mechanical.
- 4. Structure is intact, some cracks in precast
- 5. Main floor looks acceptable, no large-scale floor slab replacement required
- 6. Typical building envelope repairs and upgrades
- 7. Problematic leakage of roof at wall intersections & also at any originally-sealed penetrations
- 8. Other typical upgrades per building assessment report

Issues from 1/16/2025 meeting:

A. General

- 1. Possible grant-funded project, still being investigated
- 2. Accessible design what needs to be considered
- 3. Sustainability not LEED-certified but what needs to be considered for this project
- 4. Add in ORAT discussion early on before design process
- 5. Design to be shared with GFIAA property insurer check to see if there are any issues which insurer has identified with the FM building.
- 6. Designers will need to note setback requirements from property line and any wetlands.
- 7. CSPP where will contractor park, and stage their work and use the gates; also what will be the inconvenience for the FM team; how will work be staged so they can use a pantry, offices, meeting space, etc.
- 8. Schedule what can be done earlier before on-site construction; schedule to consider work patterns and weather.

B. Main Garage Area/Equipment

- 9. Main issue is more maintenance space needed more equipment but also more LARGER equipment longer vehicles don't fit. Some up to 78 feet
- 10. Need at least one additional lift to lift the larger equipment now that is not possible.
- 11. Better bulk fluid storage, and more oil and other storage
- 12. Other FM-related equipment (compressors etc) that need to be housed and possibly selected/procured, coordinated with other equipment and the FM team.
- 13. Car wash equipment to move and be bigger shown on concept layout as the most south new bay.
- 14. Small engine/small mower area needed maybe the bay that currently has the car wash.
- 15. Do we need more oil-water separators, or larger ones

- 16. How to better use the double-height space (mezzanine etc). this might involve elevators
- 17. Separate building issue to add onto this project Boiler in sand storage room needs to be walled off and put in a room, or otherwise addressed. It is not compatible with the sand or dust.
- 18. Adding in 4th chemical tank at Fuel Farm to be part of project

C. Offices/Bunk Rooms

- 19. Common space for training, more collaboration areas
- 20. What impact do the extra Field Maintenance FTEs have?
- 21. Now have more supervisors more offices/more private spaces
- 22. Offices are spread out all over the place
- 23. Expanded or new custodial closet
- 24. Use airport design standards for bathrooms etc.
- 25. IT is IT room big enough and does there need to be another closet?
- 26. If training room ends up with a movable partition, it does not need to be powered
- 27. Upgraded appliances in breakroom
- 28. Bathrooms for office and bunk room use to be reviewed (number, accessibility, location/use)
- 29. What does the customer non-GFIAA or guest interface look like? What kind of guests visit, how many deliveries, etc. will non-badged visitors be using the training room?
- 30. Who/how to procure furniture, what do we want. Will need office and residential furniture
- 31. More staff can locker rooms go east
- 32. Will need some sort of bunk rooms in lieu of hotel rooms like ARFF. Also need some showers etc with appropriate slope and drainage. Acoustic separation needed.
- 33. Current bunk rooms are too noisy

D. Services

- 34. Generator to be replaced. Needs to have life safety plus overhead doors. Might be able to have inverter + generator with different things on each. This needs to be reviewed
- 35. Connect fuel farm to generator or have own stand-alone generator
- 36. Also upgraded exhaust in breakroom
- 37. DAS system is there if antennas need to be moved, ATT needs to be notified.
- 38. Cameras and access control to be included to be considered in the main bay and SRE.
- 39. Add extensions for water for light washing of vehicles in each bay
- 40. Sink in each bay. Also look at chem eye washes
- 41. Contact to the BMS is to continue
- 42. consider adding sand storage to BMS.
- 43. Lighting control including bunk rooms
- 44. What is building designation with authorities having jurisdiction (Cascade Twp) will require CO monitors in bunk rooms
- 45. EV charging possibility for fleet vehicles and employee parking identifying location, possible panel sizes and future loading, and conduit runs, to future proof project
- 46. Facilities Maintenance electricians will need to review the electrical design of this project in conjunction with the existing building and the SRE.
- 47. Review at SRE project time of DTE capacity noted that this will need checking with the FM project. Also check with Consumers, however power provision is not expected to be an issue.
- 48. New efficient sanitaryware etc.
- 49. Retain TV connection via satellite dish, dish to be relocated/maybe replaced

50. Conference & training rooms to be compatible with other similar at airport – same functions, hardware, software, network

E. Building Envelope

- 51. Façade change to match SRE? It will look odd in the middle with west and east ends upgraded.

 This is a nice-to-have
- 52. Roof fall arrest extension from SRE
- 53. Dated structure, in general needs to be upgraded
- 54. Look at height limits in relation to runway should not be an issue as the SRE was not an issue, but needs checking
- 55. Taking advantage of windows for people (not storage etc)
- 56. Do the downspouts need heat tracing?

F. Site

- 57. Road from Patterson needs to be resurfaced. Also consider curbs or some sort of elevation change to reduce people going on grass
- 58. Some small entryway landscaping can likely be done in-house (might need to add some irrigation).
- 59. Snowmelt at all entrances
- 60. Signage from Patterson needs to be looked at maybe part of campus-wide wayfinding. How to keep people from thinking it is the viewing area, which is a common mistake.
- 61. Review street lighting it is still a bit dark after changing to LEDs.
- 62. Snow storage to be considered
- 63. Parking to be validated
- 64. Appropriate distances from AOA fences to be considered
- 65. Outdoor patio space on AOA side is required.
- 66. Flat slab outside building to park equipment to calibrate equipment blades, brushes etc. 40 x100 feet ideally. Could be farther away/off to side as it is flat and doesn't drain easily.
- 67. Built-in, permanent tool storage.
- 68. Can solar panels be considered somewhere?
- 69. Relocated security fence and gates to be coordinated with airport security/TSA, as well as field maintenance and the budget


G. Original building layout (for reference)

International

PROJECT NO. 98256CD

SHEET NO.

A10198256 C.DWG



Airport County

PROJECT NO. 98256CD SHEET NO.

Kent

A10298256C. dwg